

Quotation Advert

PROVINCE OF KNIKZULU-HATIL		
Opening Date:	2019-09-02	
Closing Date:	2019-09-16	
Closing Time:	11:00	
INSTITUTION DETAILS		
Institution Name:	King Edward VIII hospital	abla
Province:	KwaZulu-Natal	
Department or Entity:	Department of Health	
Division or section:	Central Supply Chain Management	
Place where goods / services is required	KING EDWARD VIII HOSPITAL MAINTENANCE	
Date Submitted	2019-08-29	# 9
ITEM CATEGORY AND DETAILS		
Quotation Number:	ZNQ: KM 242\19	
Item Category:	Services	$\overline{\mathbf{v}}$
Item Description:	CARRY OUT UPS SERVICES AS PER SCOPE OF WORK	
Quantity (if supplies)		
COMPULSORY BRIEFING SESSION /	SITE VISIT	
Select Type:	Compulsory Briefing Session	\overline{v}
Date:	2019-09-09	He
Time:	11H00	
Venue:	KING EDWARD VIII HOSPITAL OUTSIDE MAINTENANCE	
QUOTES CAN BE COLLECTED FROM:	WILL BE HANDED OUT AFTER BRIEFING SESSION	
QUOTES SHOULD BE DELIVERED TO:	KING EDWARD VIII HOSPITAL TENDOR BOX	
ENQUIRIES REGARDING THE ADVE	RT MAY BE DIRECTED TO:	
Name:	KHULANI MTHEMBU	
Email:	KHULANI.MTHEMBU@KZNHEALTH.GOV.ZA	
Contact Number:	031 360 3446	
Finance Manager Name:	MISS NOMONDE NOME	
Finance Manager Signature:		

No late quotes will be considered

Scope of work

Only qualified ups technicians must service equipment as follows: (please attach qualifications)

Ups unit

- 1. Remove batteries and carry out and applicable load test on each battery and note voltage before load test and then when on load test.
- 2. Check condition of battery terminals and clean and ghries them.
- 3. Replace all corroded cable crimp on connection to batteries.
- 4. Check and top-up electrolyte level where applicable after batteries have been fully charged.
- 5. Check battery/battery pack float charge current and note.
- 6. Check battery/battery pack current drain when ups is in full load and note (ensure load bank resistors is in a safe build unit that can not cause any fires)
- 7. Install all missing cable glands on all units.
- 8. Complete full report on non-functional (and tested) ups units and issue written condemnation certificate.

NB Note: Supervisor must be informed before and ups servicing is going to take place to give prior warning to effected wards

Service UPS units in the following areas

- A Ward
- 2. I Block (I2A)
- 3. S Block (Incide oir con alam room)
- 4. PRU/POPD
- 5. Casualty (cashers office)
- 6. A Ward
- 7. Family clinic
- Q Deathor
- 0 1
- 10. Substation 1
- 11. SOT autoclave no1
- 12. CSSD autoclave no1
- 13. Switch board