



Opening Date: 2020-07-08   
Closing Date: 2020-07-15   
Closing Time: 11:00

## INSTITUTION DETAILS



Institution Name: Nkandla hospital   
Province: KwaZulu-Natal  
Department or Entity: Department of Health  
Division or section: Central Supply Chain Management  
Place where goods / services is required: NKANDLA HOSPITAL  
Date Submitted: 2020-07-08 

## ITEM CATEGORY AND DETAILS

Quotation Number: ZNQ:  
132/2020/21  
Item Category: Select...   
Item Description: REROUTE 54MM CLASS 2 COPPER PIPE AND REPAIR DAMAGE  
CEILING BOARD AT( MATERNITY WARD)  
  
CIBD GRADE 2  
BBBEE LEVE 2  
PLUMBING CERTIFICATE

Quantity (if supplies)

## COMPULSORY BRIEFING SESSION / SITE VISIT

Select Type: Compulsory Site Visit   
Date : 2020-07-10   
Time: 11H00  
Venue: BOARD ROOM (NKANDLA HOSPITAL)

QUOTES CAN BE COLLECTED FROM:

FROM SITE

QUOTES SHOULD BE DELIVERED TO:

TENDER BOX ( NKANDLA HOSPITAL)

## ENQUIRIES REGARDING THE ADVERT MAY BE DIRECTED TO:

Name: J.N . ZULU  
Email: nobuhle.mdlalose@kznhealth.gov.za  
Contact Number: 035 8335000  
Finance Manager Name: CS 69KWA

Finance Manager Signature:

  
**No late quotes will be considered**