


LEGEND:

- B001 MAIN CLINIC BUILDING
- B002 SECURITY GATEHOUSE
- B003 STAFF RESIDENCE
- B004 STAFF HOUSE
- B005 PATIENTS TOILETS
- B006 CARPORT


KEY:

CONDITION

- As New
- Maintain
- Repair
- Replace/ upgrade
- Condemn



AVERAGE DEPARTMENT CONDITION



MHLANGANA

CLINIC KZNC205